

## 6. Operating temperature

The operating temperature ranges of the various bearings are shown in table 6.1. Should the operating temperature exceed the limits shown in the table, please contact F&T International Engineering. Stainless steel units, without seals, can operate between -20 / +120 degree °C.

**Table 6.1 Operating temperature**

Bearing type	Operating temperature
<b>KH</b>	-20 to +120 °C
<b>KB / SW..G</b>	-20 to +110 °C